





# Motor Lubrication Notice

We are continuously updating our best practices for making the most of your board and maximising its lifespan. Here is a useful tip on ensuring your board is running its best.



With the **board standing upright** on its tail, open the front main hatch and looking down inside the board, you will see the back of the motor.



Then apply lubrication to the perimeter of the center bolt. We suggest Corrosion-X 77001 Available on Amazon For best results. The board should remain standing for at least 4 hours to allow the lubricant to penetrate down through the bearings in the core of the motor. Remember, with the battery out always verify the drive line turns freely before use.

[Amazon Link](#)